

**Darlington Nuclear Generating Station REGDOC-3.1.1 Reporting  
Q1-2025**

<b><i>Report Number</i></b>	<b><i>Event Title</i></b>
D-2025-00417	Missed Predefine: Unit 0 Fire Panel Battery Replacements
D-2025-01492	Contingency Plan: Fire in Refurbishment Project Office Vestibule Heater, Safely Resolved
D-2025-01579	Unplanned Change in Reactor Power: Unit 2, Power Reduced to 93% Full Power due to leak on Relief Valve, no Operability Impact
D-2025-01601	Counterfeit, Fraudulent or Suspect Items: Lifting Eye Nuts Received, Unexpected Identification Markings and Appearance, Safely Resolved
D-2025-01698	Regulatory Interest: Ministry of Labour, Immigration, Training Skills and Development Notification, Live 600 V Electrical Cable Mistakenly Cut, no Injury to Worker and Safely Resolved
D-2025-02067	Environmental Release Control: Refrigerant Spill from Refrigeration Unit, no Environmental Impact
D-2025-03342	Degradation: Unit 2, Standby Class 3 Power System Unavailable
D-2025-04202	Licence Non-Compliance: Missed Written Notification to CNSC staff



## Darlington Nuclear Generating Station REGDOC-3.1.1 Reporting Q2-2025

<i>Report Number</i>	<i>Event Title</i>
D-2025-06724	Pressure Boundary: Carbon Dioxide Tank Exceeds Design Pressure
D-2025-08705	Unplanned Power Change: Unit 3 Power Reduction due to High Condenser Pressure, no Operability Impact



## Darlington Nuclear Generating Station REGDOC-3.1.1 Reporting Q3-2025

<i>Report Number</i>	<i>Event Title</i>
D-2025-09731	Regulatory Interest: Ministry of Labour, Immigration, Training Skills and Development Notification, Safety Incident, Load Slipped from Slings and Fell onto Floor, No Injuries and Safely Resolved
D-2025-09768	Regulatory Interest: Ministry of Labour, Immigration, Training Skills and Development Notification, Worker Injury on Uneven Surface, Fractures to Right Ankle and Left Wrist
D-2025-10475	Potential Licence Non-Compliance: Minimum Shift Complement Requirement for Unit 0 Nuclear Operators
D-2025-11759	Hours of Work Exceedance: Authorized Nuclear Operator, 16 hours of work in a 24-hour period, no Fitness for Duty Impact
D-2025-12574	Environmental Release Control: Unknown Substance Pumped Out from Unit 0 Sump 1, Safely Resolved and no Environmental Impact

**Darlington Nuclear Generating Station REGDOC-3.1.1 Reporting  
Q4-2025**

D-2025-12039	Regulatory Interest: Ministry of Labour, Immigration, Training Skills and Development Notification, Worker Injury, Employee Tripped on Metal Skid, Fractured Left Wrist
D-2025-14631	Licence Non-Compliance: Worker Entered Un-Zoned Area Without Dosimetry, no Exposure Levels or Dose Limits Exceeded
D-2025-15167	Degradation: Unit 4, Standby Class 3 Power System Unavailable
D-2025-15213	Environmental Release: Sanitary Water Spill to Yard Drainage, Safely Resolved and no Environmental Impact Observed
D-2025-15573	Unplanned Power Change: Unit 3 Shutdown Due to High Iodine-131 Concentrations, Safely Resolved
D-2025-16271	Contravention of the Licence: Main Control Room Ventilation Declared Unavailable, Safely Resolved
D-2025-16397	Contravention of the Licence: Main Control Room Ventilation Declared Unavailable, Safely Resolved
D-2025-16428	Hours of Work Exceedance: Certified Unit 0 Control Room Operator, 16 hours of work in a 24-hour period, no Fitness for Duty Impact
D-2025-16917	Unplanned Power Change: Unit 1 Transient Due to the Loss of Instrument Air, no Operability Impact
D-2025-16919	Regulatory Interest: Unit 3 Annulus Gas System Unavailable, no Operability Impact
D-2025-17144	Degradation: Impairment of Negative Pressure Containment System Based on Boundary Hole Size, no Operability Impact